

# City of Henderson Fire Safety Engineering Informational Bulletin

Issue 028

[COHFireSafety@CityofHenderson.com](mailto:COHFireSafety@CityofHenderson.com)

September 12, 2005

## FIRE INSPECTIONS UPDATE !

### N F P A 13



#### HYDROSTATIC TESTING OF UNDERGROUND LEAD-IN

Please see the attached memo for information on hydrostatic testing of all riser piping and attached appurtenances.

THERE ARE THREE OPTIONS TO CHOOSE FROM.

These options will provide avenues for contractors to determine the most convenient method for performing hydrostatic testing while ensuring inspection consistency.

### INSPECTORS' AREAS

Also attached to this Bulletin is an updated Fire Inspection Area Map.

#### FIRE SAFETY DIVISION AREA INSPECTOR GUIDE

SENIOR INSPECTOR: **ALAN LELLIS** 210-4085

|  |  |
|--|--|
| <b>Area 1:</b> <b>KEN MESSNER</b> 210-4083 | <b>Area 3:</b> <b>TERRY FUND</b> 210-4086    |
| <b>Area 2:</b> <b>MIKE STEELE</b> 210-4081 | <b>BOB WINTERS</b> 591-5857                  |
| <b>J.J. JOHNSON</b> 591-5851               | <b>Area 4:</b> <b>ROY RODRIGUEZ</b> 210-3978 |
|  | <b>BRAD STASIK</b> 591-5847                  |

#### BUSINESS LICENSE INSPECTIONS:

**J.R. JOHNSON** 591-1217

Please e-mail comments, questions & suggestions regarding this bulletin to:  
[COHFireSafety@CityofHenderson.com](mailto:COHFireSafety@CityofHenderson.com) or call 702-267-3630

If you do not wish to receive this bulletin, send a reply with REMOVE in the subject line.